



C6 Tech Tip

Courtesy of Carl Gruber

Due to a software bug, C6 Corvettes with factory navigation have had their clocks disappear after the battery has been disconnected and then reconnected. This can also affect the GPS.

I have a fix for this that I got from the Corvette Forum.

It worked for me and many others.

It's a software patch that is burned to a CD-R.

All that needs to be done is to remove the map DVD from the DVD drive and insert the CD-R with the patch. The car will recognize the patch and apply it on its own.

The car needs to be running outside and able to get the GPS signal for this to work. I have the CD-R and can give it to anyone in the club who might have the issue, or I can fix it for them free of charge.

I can burn and bring CD-Rs to the next meeting if anyone needs them.

Carl Gruber

email: carlg65@verizon.net